

**ZyXEL WRE6505 Standard Version
Release V1.00(AAQB.2)C0
Release Note**

Date: Oct 23, 2015

Supported Platforms:

WRE6505

Firmware Versions:

V1.00(AAQB.2)C0

Notes :

1. Default IP :192.168.1.2
2. Default username : admin
3. Default password :1234
4. Firmware upgrades may reset the repeater's configuration options to the factory default. Before performing an upgrade, please backup you current configuration first.

Known Issues :

N/A

Modification in 1.00(AAQB.2)C0 | 10/23/2015

1. [New Feature]: Support One Connect 2.0

zy1905 version	r6455
zy1905 suppose feature version :	
Version	2.0
L2DeviveCtrl	701
WiFiAutoCfg	1001
WiFiOnOff	1101
FwUpgrade	1501

Modification in 1.00(AAQB.1)C0 | 4/13/2015

2. [Bug Fixed]: fix Eth port disconnect issue when uplink AP changes radio (2.4G →5G or 5G →2.4G).
3. [Bug Fixed]: fix repeater auto IP issue when uplink AP is unreachable.

4. [Bug Fixed]: fix IoP issue with
 - ◆ Netgear R7500
 - ◆ Intel 6205 / Intel 7260
 - ◆ iPhone hotspot 5/5s (iOS 7.1.1/7.1.2) issue
 - ◆ Lenovo X220: Intel Advanced-N 6250
 - ◆ Lenovo X230: Intel Advanced-N 6250
 - ◆ Acer P633-M: Intel Advanced-N 6235
5. [Bug Fixed]: fix GUI issues on IE10/IE8
6. [Bug Fixed]: fix WMM issue
7. [Bug Fixed]: fix CHT MOD video issue
8. [Bug Fixed]: fix 1.00(AAQB.0)C0 reported bugs.

Modification in V1.00(AAQB.0)C0 | 4/25/2014

Initial release